## **Aircraft Specification**

Servizion

P O Box 202 204 Southgate Takanini 2246 New Zealand Tel: +64 9 296-1630 Mob: +64 27 4965867 Email: sales@premi-air.com WhatsApp +64 27 496 5867

December 2031

## 2005 Robinson R44 Clipper II

MODEL NO. DATE OF MANUFACTURE COLOUR	R44 Clipper II 2005 White	<b>REGISTRATION NO</b> VH-IIQ <b>SERIAL NO</b> 10747 <b>TOTAL TIME AIRFRAME</b> 3,308 Hrs
<b>COMPONENT TIMES REMAINING AS AT:</b> 25 March 2024		
M/R Blades	531 /531	GENERAL CONDITION
M/R Spindles	531 / 531	
M/R Shaft	531	Paintwork Good
M/R Swashplate	531	Windows Good
M/R Gearbox	531	Interior Good
M/R Hub	531	
Horizontal Stabiliser	1,091	<b>12 Year Insp. Due</b> August 2029
T/R Gearbox	531	<b>2,200 Hr Insp. Due</b> 3,840 hrs T.T.
T/R Blades	1,711 /1,711	
T/R Hub	1,711	
T/R Driveshaft	531	<b>OPTIONAL EXTRAS FITTED</b>
T/R Pitch Control	531	Dual Controls
Tail Cone	1,071	Nat AA12S Audio
Governor Controller	531	King KY196A VHF/Comm
Upper Frame Assembly	531	Garmin GNC420 Nav/Com/GPS
Clutch Assembly	531	King GTX330 Transponder
Clutch Actuator	531	LED Landing Lights
Hydraulic Pump & Reservoir	531	Pop-out floats
Hydraulic Servos	531	406 ELT
Fanwheel Assembly	531	
1 an wheel Assembly	551	

**Engine Time to Overhaul** 

1,091 Hrs **12 Yearly due** 

PRICE\$465,000PLUS GSTE&OEThis specification has been prepared from information supplied by the vendor. This company makes no<br/>representation as to its accuracy and it is the buyer's responsibility to ensure the aircraft and its components<br/>are as described.